

REPORT OF THE
INVESTIGATION INTO
THE CASUALTY INVOLVING
MR. JOHN ALLEN AT BULLS
MOUTH, CO. MAYO ON THE
19TH MARCH 2003

The Marine Casualty Investigation Board was established on the 5th, June 2002 under The Merchant Shipping (Investigation of Marine Casualties) Act 2000

The copyright in the enclosed report remains with the Marine Casualty Investigation Board by virtue of section 35(5) of the Merchant Shipping (Investigation of Marine Casualties) Act, 2000. No person may produce, reproduce or transmit in any form or by any means this report or any part thereof without the express permission of the Marine Casualty Investigation Board. This report may be freely used for educational purposes.







1.	SYNOPSIS.	4
2.	FACTUAL INFORMATION.	5
3.	EVENTS PRIOR TO THE INCIDENT.	6
4.	THE INCIDENT.	7
5.	EVENTS FOLLOWING THE INCIDENT.	8
6.	CONCLUSIONS.	9
7.	RECOMMENDATIONS.	10
8.	APPENDICES.	11
9.	INDEX OF CORRESPONDENCE	20

SYNOPSIS

1. SYNOPSIS.

1.1 On the 19th March 2003 Mr. John Allen left his town house in Westport and boarded the Achill Island bus. He walked from the bus stop to Bulls Mouth. At about 1750 hours Mr. Allen departed from the slipway at Bulls Mouth for Inishbiggle Island. When Mr. Allen had not arrived at his house on Inishbiggle Island by 2200 hours neighbours became concerned and at 2235 hours approximately the Garda Siochana at Westport were contacted.

At 2235 hours the Gardai at Westport contacted MRCC.

Mr. John Allen remained missing until the 1st August 2003 when his body was found at Doohama, Co. Mayo.





2. FACTUAL INFORMATION

2.1 Mr. Allen's vessel is an open boat of timber construction. The boat is clinker built with steamed timbers (frames) and seven planks from keel to gunwale. The vessel is in reasonable condition. (See Appendix 8.1 & 8.2.)

Length overall: 4.24 metres
Breadth: 1.37 metres
Depth: 0.41 metres

Thwarts: 2 of

Oars: 2 off, 2.4 metres long

Rowlocks: 2 off

The engine was not located after the incident. I understand that it is an elderly single cylinder Seagull outboard engine. This type of engine has an output of about 1.6-horse power.

EVENTS PRIOR

3. EVENTS PRIOR TO THE INCIDENT

- 3.1 Mr. John Allen was an experienced yachtsman.
- 3.2 Mrs. Donna Allen rarely went to their property on Inishbiggle Island. On the days that Mr. Allen would travel to the island it was a standing arrangement that Mrs. Allen would telephone the house on the island at 1900hours.
- 3.3 On the 19th March 2003 Mr. Allen left the house in Westport at 1430 hours and boarded the 1500 hours bus. Mr. Allen was carrying a two-wheel trolley, a roll of plastic and an umbrella. The bus would pass Bulls Mouth's school at about 1645 hours. Mr. Allen would alight from the bus at this point and walk the fifteen-minute journey to the slipway at Bulls Mouth, Achill Island where he kept his boat and outboard engine.



4. THE INCIDENT

- 4.1 On the19th March 2003, 1950 hours, Mr. Allen was observed leaving the slipway at Bulls Mouth with the outboard engine operating (See copy of chart of area at Appendix 8.3). The weather was good (see Appendix 8.4 for the Sea Area Forecast which was issued at 1800 hours on the 19th March 2003). The Tidal conditions indicated the tide was flooding with high water at 1900 hours.
- 4.2 A short time later the engine was heard to stop. The vessel was now in front of the first house south of the slipway. The tide was coming in, from north to south direction. Mr. Allen was observed going from the stern of the boat to the bow where he began to unwind a line from a wooden frame into the water. Everything appeared normal and there was no reason for concern. At 1900 hours there was no sign of the boat, there was nothing on the bay and it was assumed that Mr. Allen had gone around the South side of the Island to his home.
- 4.3 Mrs. Allen telephoned their house on Inishbiggle Island at 18.55 hours but there was no reply. Mrs. Allen continued to try and contact her husband but without success.
- 4.4 The Gardai at Westport were contacted at 2235 hours. The Gardai contacted MRCC at 2235hours.
- 4.4 The rescue services responded immediately and a search of the area commenced.
- 4.6 At 0213hours on 20th March 2003 the empty, partially sunk boat, was located in position 54.03 095N 0059.36W, which is 1.25 miles Northwest of Ridge Point, Achill Island.
- 4.7 On the 21st March 2003 a small black / grey hold all and other items were found in search area. These items belonged to Mr. Allen.
- 4.8 The search continued each day until 30th March 2003 and resumed the following weekend but Mr. Allen's body was not located.

EVENTS FOLLOWING

5. EVENTS FOLLOWING THE INCIDENT

- 5.1 Although the main search was scaled down local people continued to search for Mr. Allen.
- On the 1st August 2003 Mr. Allen's body was recovered on Roy Beach, Doohama, Co. Mayo. The body was removed to Mayo General Hospital, Castlebar and was identified as that of Mr. John Allen, Westport, Co. Mayo.



6. CONCLUSIONS AND FINDINGS

- 6.1 There can be a 6-knot current at Bulls Mouth depending on tidal conditions. A 1.6 hp engine is quite small for conditions such as this. On the day in question the engine stopped a short time after departure from the slipway. It is not known if the engine was restarted. The partially sunk boat was located about eight hours later. The engine was not located.
- 6.2 It is believed that Mr. Allen was not wearing a lifejacket.
- 6.3 One can only assume that Mr. Allen entered the water either by falling in or as a result of the boat becoming swamped.

RECOMMENDATIONS

7. RECOMMENDATIONS

- 7.1 Lifejackets or personal floatation devices should always be worn when on open decks or on an open boat.
- 7.2 On all voyages to sea, estuaries and lakes distress signals and suitable means of communication should always be carried.
- 7.3 Where voyages are undertaken alone contact should be maintained with a person ashore either by sight or other means of communication.




8. APPENDICES

- 8.1: Photographs of vessel
- 8.2 Photographs of vessel
- 8.3 Chart of Area
- 8.4 Sea Area Forecast

APPENDIX 8.1

8.1: Photographs of vessel






8.2 Photographs of vessel





8.3 Chart of Area





8.4 Sea Area Forecast

Warning of heavy Atlantic swell: NIL

Text of Gale warning	
NIL	

Coastal Reports	at 6 pm	
Malin Head West, 2 Knots, Mist, 3 Miles, 1028, Steady		
Rosslare	South-Southwest, 4 Knots, Mist, 1.3 Miles, 1030, Falling slowly	
Roches Pt (Automatic)	Southwest, 8 Knots, 9 Miles, 1030, Steady	
Valentia South, 6 Knots, Cloudy, 6 Miles, 1030, Steady		
Belmullet South, 12 Knots, Mist, 6 Miles, 1028, Falling slowly		
Dublin Airport Southeast, 5 Knots, Mist, 1.6 Miles, 1030, Falling slowly		
Buoy M1 53.1N, 11.2W	South-Southwest, 16 Knots, WAVE HT 2.2 m, 1028, Steady	
Buoy M2 53.5N, 5.4W	South, 5 Knots, WAVE HT 0.4 m, 1030, Steady	
Buoy M3 51.2N, 10.50W South-Southwest, 5 Knots, WAVE HT 1.9 m, 1030, Steady		

Sea Crossings	State of sea for the next 48 hours
Dublin - Holyhead	Slight.
Rosslare - South Wales	Slight.
Cork - South Wales	Slight.
Rosslare - France	Slight to moderate.
Cork - France	Slight to moderate.

Next update before 0100 hours

A detailed forecast may be obtained by dialling *Weatherdial* on 1550 123 855. Calls cost € 0.73 per minute (Incl. VAT).

©2003 Copyright All Rights Reserved. Met Éireann (Department of the Environment and Local Government)

WEI OFFICE

84:81 8005 .tsM.81

2 'd 0979'ON

Page MBZ

12207E9470

TEPHULTCSID

03/16/03 SS:15:14

06:08 FAX 353 1 6620795 MRC

MRGAT DUBLIN

→→→ MALIN HEAD MKSC No.9030 P. 1/1

MONT



General Forecast Division

Fax: (01) 8064275

Tel: (01) 8064255

Forecast for Belmullet Bay.

Fax To: 07770221

Issued at 04:56 23-Mar-2003

Forecast for today, Sunday, 23-Mar-2003

Wind(Beaufort) : Southeast to east 2 or 3

Weather

: Fair

Visibility Sea State : Good : Calm or rippled

©2003 Copyright All Rights Reserved. Met Éireann (Department of the Environment and Local

Government)



RI 20:25 FAX 353 1 6620795

MR(A) DUBLIN

No.8803 P. 1

間001



General Forecast Division

Fax: (01) 8064275

ME 353 1 6620795

Tel: (01) 8064255

Forecast for Blacksod Bay

Time of Issue: 20:30, Friday, 21/Mar/2003

Fax No.: #003

Forecast for period 0900 hrs to 2400 hrs Saturday, 22-Mar-2003

Wind	1:	South force 5, later decreasing force 3.
Weather	1:	Mostly dry, (a little mist or drizzle possible).
Visibility	:	Moderate to good.
State of Sea	:	Southwest Sea / Swell of 3 to 4 metres (open sea).

©2003 Copyright All Rights Reserved. Met Éireann (Department of the Environment and Local Government)

20/03 03 06:52 FAX 00 353 61 712962 MET SH/A:NON 00 353 61 712962 MET EIREANN FORECAST FOR SEARCH/RESCUE AREA SSUE TIME/DATE 06:40 UTC -- 20 March 2003 OCATION :FINNER TO ACHILL SOUND/90 MILES NW EAGLE ISO ERIOD OF VALIDITY :0600-1000 VINDS SURFACE: BETWEEN 31010KT AND 25010KT VINDS 1000 FT: 25010-15KT /ISIBILITY: 1500-3000M LOC 0500M AT FIRST OVERLAND OTHERWISE LOUD AMOUNTS AND HEIGHT OF BASES: SCT500FT BKN1000FT LOC BKN 200FT AT FIRST OVERLAND, OTHERWISE SCT1500FT BKN3000FT WEATHER: MIST/DRIZZLE AT FIRST E CONNACHT/DONEGAL WITH FOG ON HILLS REEZING LEVEL :6000FT MSL PRESSURE:1027-1030HPA AIR TEMP. :6-10 C SEA TEMP. :9/10 C STATE OF SEA :SLIGHT IN ACHILL SOUND IODERATE (2M) SWELL 90 MILES NW EAGLE ISLAND STATE OF GROUND: ADDITIONAL INFORMATION: Issued By : at 06:48 UTC on 20 March 2003 MET Eireann, Aviation Services Division, Shannon Telephone No. 061-471439 Telefax No. 061-472737

Ø 001





10/03 '03 WED 23:32 FAX 00 353 61 712964 MEJE SHANNUN →→→ MALIN COASIGUARD @1001

00 353 61 712964

MET EIREANN FORECAST FOR SEARCH/RESCUE AREA

ISSUE TIME/DATE 23:21 UTC -- 19 March 2003

OCATION :SHANNON TO ACHILL

PERIOD OF VALIDITY:19/2300 TO 20/0300

WINDS SURFACE: 19010KT BECMG 25010KT

WINDS 1000 FT: 24010-15KT

VISIBILITY: 3000M-8KM OCNL 1500M

CLOUD AMOUNTS AND HEIGHT OF BASES: FEW1000FT BKN 4000FT OCNL

SCT500FT BKN1000FT

WEATHER: MIST OCNL DRIZZLE

FREEZING LEVEL :6000FT

MSL PRESSURE :CIRCA 1030HPA

AIR TEMP. :6-9 C

SEA TEMP. :10 C

STATE OF SEA: SLIGHT TO MODERATE

STATE OF GROUND :

ADDITIONAL INFORMATION:

Issued By : at 23:26 UTC on 19 March 2003



CORRESPONDENCE

9. INDEX OF CORRESPONDENCE RECEIVED

Correspondent	Page No.
Mrs. Donna Allen	21
MCIB Response	22
Mr. Thomas Calvey	23
MCIB Response	24
Irish Coast Guard	25
MCIB Response	26



Mrs. Donna Allen

•	Brevard Molwolina Dec. 3.03
	Der Mr. Heron,
	Thank you very much for the marine Blood, that have just gatter teday. Leaish to thank wayne again for the help in the long search for my known, John alle. and thank you for the mejore tro. I have done a lot of sailing in my life soil understand the
	Sinserely, Down a allen (Mrs. John Ollen)
	EIRE

CORRESPONDENCE

MCIB Response

MCIB RESPONSE TO THE LETTER FROM MRS. DONNA ALLEN OF 3RD DECEMBER 2003.
The MCIB notes the contents of this letter.





Mr. Thomas Calvey



Thomas J. Calver Bullsmouth RD Dooniver Adrill

> Co Mayo 8-12-2003

I Thomas Calvey would like to state that I have no comments or observations to offer on the draft report of the investigation in to the casualty involving MR John AllEN at the Bullsmouth, co MAYO on the 19th MARCH, 2003.

Thomas J. Calvet.

CORRESPONDENCE

MCIB Response

	RESPONSE TO THE LETTER FROM MR. THOMAS CALVEY HELD DECEMBER 2003.	Y
The MC	IB notes the contents of this letter.	





Irish Coast Guard



Mr Dick Heron

Secretary
Marine Casualty Investigation Board
Department of Communications,
Marine & Natural Resources
Leeson Lane
Dublin 2.

28th Nov. 2003.

Re MCIB 77 Draft Report on drowning at Bull's Mouth 19th March 03.

Dear Mr Heron,

The Irish Coast Guard has no comment or observation to make concerning this report.

Yours sincerely,

Eamon Torpay

SAR Operations Manager IRCH HQ.

CORRESPONDENCE

MCIB Response

	ESPONSE TO THE LETT H NOVEMBER 2003.	ER FROM IRISH C	OAST GUARD
The MCIE	notes the contents of this	letter.	









NOTES

